App. F. IX-4

1929-30 (Medical)

File No. 49-25

Previous References
Med. 49-25 (5, 26, 54, 55, 56, 57, 58, 71, 106, 110 to 113, 115 + 117)

Serial Nos. 120, +121

Later References

General and Revenue Secretariat.

Serial Nos. 2

Part B for December 1929

SUBJECT

Regarding the improvements to the District Hospital Building at Kolar

Sl. 121.

Dated, Kolar, the 17th January 1929.

From

C. B. Gopala Rao, Esquire,

President, District Board, KOLAR.

To R. RANGA RAO, ESQUIRE, B.A., B.L.,

Secretary to the Government of Mysore,

GENERAL Department, **BANGALORE.**

Thro' (The Deputy Commissioner, Kolar District.)

med. 49-25-120.

Sir,

With reference to memo No.G.5645-7 dated the 10th November 1928 forwarding copy of your letter No.G.5644/med. 49-25-117 dated the 10th idem to the Chief Engineer of Mysore stating that the question of effecting improvements to the District Hospital building at Kolar may lie over, I have the honour to forward herewith a copy of the resolution No.35 of the Kolar District Board passed in their meeting held on the 20th ultimo and to state that there is great necessity for the improvements and it is to be regretted that the question has to lie over.

Memo forwarded with Compliments.

I have the honour to be,
Sir,
Your most obedient servant,

C B Gopala Rao
President,
District Board, Kolar.

K.M.R.

Dy. Comm.

Submit for orders with papers

was not this ordered to lie over as a result of the unwilling question of the Local Bodies? Also write a draft reply to above effect.

Please see Memo is not complete Dft. prepared accordingly

Dy: record as per file
keeping others in view.

19/2/79

(Vasee)

25/2/79.

Sa.121 To the President, District Bd: Kolar.
thro' the Dy: Commr: Kolar

No: S10999 dy 2.3.79

Enquiries of the local bodies
are willing to contribute towards
the cost of improvements to the
Dr. Hospl: at Kolar.

4.3

PROCEEDINGS OF THE KOLAR DISTRICT BOARD MEETING

HELD ON THE...20th December 1928.

XX XX XX

No.35 Secretary's letter No to drop the construction of wards in the District Hospital,Kolar, D 2 Dis.No.91/28-29-

Resolution.

Recorded. This is a great necessity and the Board regret that the matter is dropped .

XX XX XX

"EXTRACT"

C.R.Gopalakrishna Rao

PRESIDENT,

District Board Kolar,

Serial No.

Letter No. D.2 Dis. 9/29-30 dt 5/8th July 29
from the President, Dist Board, Kolar,
Stating that the Dist Board, Kolar have resolved to abide by their resolution dt 5.11.27 in the matter of Contribution towards the cost of improvement to the Civil Hospital, Kolar.

Subst:-

In their resolution dt 5.11.27, the Dt Board, Kolar agreed to pay 1/3 of the cost viz 14,000/-. A revised Estimate amounting to Rs. 23,600/- was received from the Chief Engr. with his letter dt 12.5.28. The D.B., being consulted again whether they would bear 1/3 of the revised estimate, pleaded their inability to pay more than resolved on 5.11.27. vide Resolu. dt 9/10th Aug 1928. Since the local bodies pleaded inability to bear their Shares of Cost, the matter was ordered to lie over. vide letter dt 10.11.28.

The District Board is time and again urging for effecting the improvements to the Hospitals but at the same time plead inability to pay its Share of Cost. Submd for orders with reference.

Sup K
13/7

NOTE—Contn. sheet

Serial No.

The Dist: Board is not agreeable to pay their quota on anything more than Rs 14,000. (The revised estimate is Rs 23,600). In the circumstances, whether it is possible to restrict the contemplated improvements to the Civil Hospital to the extent of Rs14,000 is a point for consideration. (The necessity for urgent improvements is admitted by the Dist: Bd:).

The present Senior Surgeon's views may perhaps be called for unofficially.

13/7

Chief Secy)

Yes

Rg

26/7/29.

Forwarded with Compliments, U.O. to the Senior Surgeon, for favor of opinion.

By order

27. 7. 1929.

for Ch: Secy.

CHIEF SECRETARY.
15 JULY 1929

U.O. 12/MD of 27-7-29

W.O.C.627-4/11.11.29.

CHIEF SECRETARY.
12 NOV. 1929

I enclose copy of a D.O. letter dated the 7th Instant, received from the Superintending Engineer, Mysore Circle, Mysore, on this subject. It will be seen that the estimate is made up of two portions- one for improvements to the Hospital amounting to Rs.7470/- and the other for providing additional buildings at a cost of Rs.16,130/- . I think that all improvements aiming at mere architectural effect may be dropped for the present. It would quite do

WD 01684—GPB—30,000—20-1-29

Serial
No.

do if an additional building conforming exactly to the one recently added to the District Hospital at Tumkur is put up. This would in all probability not cost very much more than the sum agreed to by the District Board. I request further instruction in the matter.

The plans and estimates are enclosed for reference.

RC/13/11/29

S. Subba Rao.
Senior Surgeon.

Perhaps the S.S. may be requested to get a revised plan & estimates in consultation with the Chief Engineer, limiting the cost to about the sum agreed to by the D-B.

13/11

Chief Secy)

Rec'd from C.S. 19/11

CHIEF SECRETARY. 14 NOV 1929

The position as stated by the Surgeon may be intimated to the Dist Bd and they may be asked if they would be content with only an additional building which would cost Rs 16230 and whether they would be agreeable to pay another of this amount

Hd Member.

4964/23/11

22/11

General and Revenue Secretariat. File No. of 192 .

Serial No.

It is not the D.S.S. only that is concerned, but the Mal Cl also. Not (Mark therefore it is better for S.S. to correspond with the local bodies & address first, instead of first writing to local bodies & S.S.) Please inform S.S. that until the Mal Cl is in a position to pay its quota of the cost, there does not appear to be any use in pursuing the matter

by
25-11-29

Draft. DD 30/11

RG 29/11/29

Send with a draft.

DD 3/12

I think the 2nd para: of the draft is not req: I shall DD 3/12

To. The Senior surgeon
No Q. 7051 dt 7.12.29

States that until the Mal council is in a position to pay its quota of the cost there is no use in pursuing the matter

NOTE—Contn. sheet.

WD 066—GPB—30,000—26-7-29

General and Revenue Secretariat. Med File No. 49 of 1925.

Serial No.

"S"

From the Dy Comm Kolar Dt
No A.S.C 1196/28-29 Dt 27-11-25.
Forward a copy of the resolution of the Town Municipal Council, Kolar pleading inability to contribute on account of the strained finances of the Council in as much as they had paid their Quota of Contribution towards the Cost of the Female Dispensary building which was sanctioned.

In this office office letter No G 7051 dtd 4.9.25 & 7-12-25 the Sr Surgeon was informed that there is no use in pursuing the matter until the Mal. Cl. is in a position to pay its quota of the Cost.

A copy of the reply given to the Sr Surgeon may be sent to the Dy Comm for Communication to the Municipal Council

Submitted for orders.

KD 9/12/25

This is in reply to this office Communication.

No further action appears to be req: as the S.S. has already been informed that the matter need not be pursued like the Mal: Cl: is able to rep. (Genl: Secy)

Dy 10/12

NOTE—Contn. sheet.

WD 066—GPB—30,000—26-7-29

PD 11/12/25

Section Med

File No. GG - 25

Serial No. 121

No. G. 10999.

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

the *192*

Date of issue 2-3-29.

Signed by M. M. Jr

List of enclosures.....

Copied by.....

Examined by.....

To

The President, Distt Bd
Kolar Distt/

thro' the Dy Com Kolar

Sir,

With refce to your letter
No 190/28-29 dt 17th Jan 29
regarding improvement to the
Distt Hospl building at Kolar,
I am directed to state that
the question was ordered to lie
over owing mainly to the inability
of the Municipal Council and Commissioners of the Dis Board
~~of the local bodies~~ to bear their
their quota of contribution
towards the cost, as already
stated in this office letter

No 5644/Med 29-25-11)

D 10th Nov 1928 Communicated
under Memo No 56457
of the same date.

I am to add that if the local bodies are willing to bear their share of the cost, the question will be taken up for Dhanbad
consideration.

2/11 Secretary to Govt

W.O.M.S.S. 25-29

GENERAL MISCELLANEOUS BRANCH

Office of the President, District Board,
Kolar District,

Dated, Kolar, the 18th May 1929

From

Gm. 8485

C. B. Gopala Rao Esquire,

President, District Board, **KOLAR.**

To

The Chief Secretary to the
Government of Mysore, Bangalore.

Gm 21/5/29 Sis

Referring to your letter No.G.13956-7 Med.49-25 dated the 17th instant, regarding contribution to the improvements of the Civil Hospital at Kolar, I have the honour to state that the question was not considered by the Board in the last meeting for want of time and that it will be considered in July next and their views communicated thereafter.

I have the honour to be,
S i r,
Your most obedient servant,

C B Gopala Rao

P r e s i d e n t,
District Board, Kolar.

dd 21/5

Ngm

further report will be awaited till 20/7/29 & appl dd 23/5

D 23-5-29 KP

D2 Di 9/29-30

Office of the President, District Board,
Kolar District,

Dated, Kolar, the 5th July *192*9

Med 49-25.

From

C. B. Gopala Rao Esquire,
President, District Board, **KOLAR.**

GENERAL MISCELLANEOUS BRANCH
11 JULY 1929

To

The Chief Secretary to the Government
of Mysore, Bangalore.

Sir

With reference to your letter No.G.13956-7/Med.49-25 dated the 17th May 1929 regarding the contribution from the Board towards the contemplated improvements to the Civil Hospital at Kolar, I have the honour to state that the Board in their meeting of the 24th ultimo have resolved to abide by their resolution No.13 dated the 5th November 1927 to contribute a third of the estimated cost of Rs.14,000/-

2. Copy of their resolution No.14 is enclosed.

3. The Board is of opinion that Kolar Civil Hospital being a District Civil Hospital the Government should

should bear the remaining portion.

I have the honour to be,
S i r,
Your most obedient servant,

Ramaiah Rao

for P r e s i d e n t,
District Board, Kolar.

PROCEEDINGS OF THE KOLAR DISTRICT BOARD MEETING

HELD ON THE 24th June 1929. 14.

XX XX XX

No. 14. Letter No.G.13956-7 Med. 49-25 dated 17-5-29 from the Chief Secretary to Government, re: the contribution towards the cost of the improvements to the District Hospital, Kolar.

Resolution The Board are agreeable to bear a third of the cost of the original estimates as already agreed to and request that the Government may bear the balance of the cost as this is a District Hospital.

XX XX XX

"EXTRACT"

PRESIDENT,
District Board, Kolar.

D.O. Letter No. 239, dated 7th November 1929 from the Superintending Engineer, Mysore Circle, to the Senior Surgeon in Mysore.

Your D.O.No.C. 627-1, dated 10th September 1929, retarding the proposed addition to the Civil Hospital, Kolar.

The estimate of Rs. 23,600/- herewith returned is not merely for the simple addition of a block of three rooms with verandahs in front and rear as observed by you but it includes the cost of improvements amounting to Rs.7,470/- to treat the existing building as per the approved design furnished by the Architect. The improvements consist of remodelling the whole roof with new wood work, the hall portion being tiled and the verandhas provided with terraced roof.

The cost of the additional buildings proper will be Rs.16,230/- for a plinth area of nearly 3200 sq. feet which works to be Rs.5/- per s.ft.

There are certain structural differences between the buildings as constructed at Tiptur and the one proposed for Kolar. While brick in mud is used in the former, brick in mortar is proposed in the latter. While Mangalore flooring tiles are provided for in the former marceilles tiles are provided for in the latter. Very high class work is provided for in the estimate for the Kolar Hospital extension. Cement plastering and oil painting have been proposed for the walls and an ornamental terrace verandha has been included in the design. As the Hospital will face the important Madras-Bangalore Road, a nice elevation is called for in my opinion.

I find that a depth of 5' has been proposedfor the foundation this of course depends on the soil. If a hard soil is met with the depth will be reduced. If Marceilles tiles flooring is not required and if the depth of foundation is also reduced and several slight changes are made re. the material for plastering, the estimate amount for the additional ward may with suitable reduction of rates be brought down by Rs.2,500/- Similar reduction for improvements for the existing portion may effect a savings of Rs.750.

If you consider that a thorough change in the design is necessary, I request you will send a sketch showing your requirements when a fresh plan and estima e will be ordered to be prepared.

The enclosures to your letter are herewith returned.

Copy.

S. Subbarao
Senior Surgeon.

Details of work.		No.	Dimensions			Contents	Total.	
Earthwork excavating foundations.								
Main wall.	longitudinal walls.	2	$73\frac{5}{8}$	3	5	2209		
	Cross wall	2	$14\frac{1}{2}$	3	5	435		
		1	$14\frac{1}{2}$	$2\frac{5}{8}$	5	190		
	Cross wall at the end.	1	$21\frac{1}{2}$	3	5	322		
front and rear verandah.	longitu	2	$76\frac{5}{8}$	$2\frac{5}{8}$	5	2011		
	Cross wall in rear (nurse room)	2	$7\frac{7}{8}$	$2\frac{5}{8}$	5	207		
extra thickness in rear of central room in verandah.		1	$20\frac{1}{2}$	$\frac{3}{8}$	5	38		
	Cross walls	2	$7\frac{7}{8}$	3	5	236		
	partition wall.	1	$7\frac{7}{8}$	$2\frac{1}{4}$	5	89		
Cross wall in front verandah.		1	$6\frac{7}{8}$	$2\frac{5}{8}$	5	90		
extra portions at the corners.		2	$3\frac{3}{4}$	$\frac{3}{8}$	5	14		
latrine and bath rooms (alround)		1	$50\frac{3}{4}$	$2\frac{5}{8}$	5	333		
	passage	2	$5\frac{3}{8}$	$2\frac{5}{8}$	5	141		
extra thickness in the centre of front verandah.		1	$21\frac{1}{2}$	$\frac{3}{8}$	5	40		
front parch.	Corner Walls	2	$13\frac{1}{2}$	$1\frac{1}{2}$	5	101		
front steps.	centre	1	11	$2\frac{1}{2}$	$\frac{1}{2}$	14		
	side	1	$12\frac{1}{2}$	$2\frac{1}{2}$	$\frac{1}{2}$	16		
rear steps		1	4	$2\frac{1}{4}$	$\frac{1}{2}$	5		
Total.						6491	qds	240
2 Burnt Stone in mortar.								
Foundation 1 step. main wall.	longitudinal.	2	$73\frac{5}{8}$	3	$2\frac{1}{2}$	1104		
	Cross walls.	2	$14\frac{1}{2}$	3	$2\frac{1}{2}$	218		
		1	$14\frac{1}{2}$	$2\frac{5}{8}$	$2\frac{1}{2}$	95		
	at the end	1	$21\frac{1}{2}$	3	$2\frac{1}{2}$	161		
front and rear verandah walls.		2	$76\frac{5}{8}$	$2\frac{5}{8}$	$2\frac{1}{2}$	1006		
Cross wall in rear (nurse room)		2	$7\frac{7}{8}$	$2\frac{5}{8}$	$2\frac{1}{2}$	103		
extra thickness in rear of central room in rear verandah.		1	$20\frac{1}{2}$	$\frac{3}{8}$	$2\frac{1}{2}$	38		
Cross walls in rear verandah.		2	$7\frac{7}{8}$	3	$2\frac{1}{2}$	118		
	partition wall.	1	$7\frac{7}{8}$	$2\frac{1}{4}$	$2\frac{1}{2}$	45		

	2	3 1/4	5/8	2 1/2	7
latrine and bath rooms alround.	1	50 3/4	2 5/8	2 1/2	166
passage	2	5 3/8	2 5/8	2 1/2	71
extra thickness in the centre of front verandah	1	21 1/2	3/8	2 1/2	20
porch.					
steps. front. centre.	1	~~1 3/2~~ 1 1/2	1 1/2	2 1/2	51
side.	1	11	2 3/4	1/2	15
steps rear.	1	12 1/2	2 3/4	1/2	17
foundation II steps. main wall longitudinal.	1	4	2 1/4	1/2	5
Cross wall.	2	~~74 1/2~~ ~~3/8~~	2 1/2	2 1/2	923
" "	2	15	2 1/2	2 1/2	187 ~~112~~
" " end.	1	15	2 1/8	2 1/2	80
front and rear verandah walls.	1	21	2 1/2	2 1/2	131
rear verandah. Cross walls (nurse room)	2	76 ~~5/8~~	2 1/8	2 1/2	810
extra thickness in rear of central rooms.	2	8 3/8	2 1/8	2 1/2	89
Cross walls.	1	20	3/8	2 1/2	19
partition wall.	2	8 3/8	2 1/2	2 1/2	105
Cross wall in front verandah.	1	8 3/8	1 3/4	2 1/2	37
extra thickness at the Corners.	1	7 3/8	2 1/8	2 1/2	39
porch.	2	3 1/2	3/8	2 1/2	7
extra thickness in front verandah.	1	~~1 1/2~~ 13	1 1/2	2 1/2	49
latrine and bath room in rear alround.	1	21	3/8	2 1/2	20
passage.	1	50 3/4	2 1/8	2 1/2	270
Basement:- main wall longitudinal.	2	5 7/8	2 1/8	2 1/2	62
Cross wall.	2	74 5/8	2	1 1/2	448
	2	15 1/2	2	1 1/2	93
	1	15 1/2	1 5/8	1 1/2	38
at the end	1	20 1/2	2	1 1/2	62
front and rear verandah walls.	2	76 1/2	1 5/8	1 1/2	373
cross walls. Division	2	8 7/8	1 5/8	1 1/2	43
extra thickness in rear of central rooms.	1	19 1/2	3/8	1 1/2	11
Cross walls.	2	8 7/8	2	1 1/2	53
partition wall.	1	8 7/8	1 1/4	1 1/2	17
front verandah. Cross wall.	1	7 7/8	1 5/8	1 1/2	19
extra thickness at the Corners	2	3 1/4	3/8	1 1/2	4
do — in the front	1	20 1/2	3/8	1 1/2	12
porch.	1	~~1 1/2~~ 12 1/2	1 1/2	1 1/2	~~28~~

					$1\frac{1}{8}$	$\frac{1}{2}$	31	
3	Steps front centre	I steps.	1	$10\frac{1}{2}$	3	$\frac{1}{2}$	16	
		II "	1	$8\frac{1}{2}$	2	$\frac{1}{2}$	9	
		III "	1	$6\frac{1}{2}$	1	$\frac{1}{2}$	3	
	side	I steps	1	12	3	$\frac{1}{2}$	18	
		II "	1	10	2	$\frac{1}{2}$	10	
		III "	1	8	1	$\frac{1}{2}$	4	
	steps rear.		1	$3\frac{1}{2}$	2	$\frac{3}{4}$	5	
		Total.					7459	
	Deductions:-						7534	
	front verandah retaining wall.		1	$57\frac{1}{8}$	$1\frac{5}{8}$	$\frac{1}{2}$	46	
	Cross wall.		1	6	$1\frac{5}{8}$	$\frac{1}{2}$	5	
	porch.		1	9	$1\frac{5}{8}$	$\frac{1}{2}$	7	
	rear verandah retaining wall.		1	47	$1\frac{5}{8}$	$\frac{1}{2}$	38	
	passage.		2	$6\frac{3}{8}$	$1\frac{5}{8}$	$\frac{1}{2}$	10	
	cills of doors.		10	$5\frac{1}{2}$	2	$\frac{1}{2}$	55	
	-do-		1	$5\frac{1}{2}$	$1\frac{5}{8}$	$\frac{1}{2}$	4	
	-do-		3	4	$1\frac{5}{8}$	$\frac{1}{2}$	10	
	steps front centre.	I steps.	1	$14\frac{1}{2}$	1	$\frac{1}{2}$	7	
		II "	1	$10\frac{1}{2}$	1	$\frac{1}{2}$	5	
		III "	1	$6\frac{1}{2}$	1	$\frac{1}{2}$	3	
	side	I "	1	16	1	$\frac{1}{2}$	8	
		II "	1	12	1	$\frac{1}{2}$	6	
		III "	1	8	1	$\frac{1}{2}$	4	
	rear steps.		2	$3\frac{1}{2}$	1	$\frac{1}{2}$	4	
		Total					212	
	Balance burnt stone in mortar						7322	7322
3	Burnt brick in mortar.						7247	cft. 7247
	Superstructure:- Main wall longitudinal.		2	$75\frac{1}{8}$	$1\frac{1}{2}$	$13\frac{1}{2}$	3043	
	Cross walls.		2	16	$1\frac{1}{2}$	14	672	
	"		1	16	$1\frac{1}{8}$	14	252	
	" at the end.		1	20	$1\frac{1}{2}$	14	420	
	gables.		2	16	$1\frac{1}{2}$	$\frac{16}{6}$	128	
	-do-		1	16	$1\frac{1}{8}$	$\frac{16}{6}$	48	
		C. O.					4563	

" Cross wall.	2	$9\frac{3}{8}$	$1\frac{1}{8}$	$9\frac{7}{12}$	202
linen and nurse rooms Cross wall.	2	$9\frac{3}{8}$	$1\frac{1}{2}$	$9\frac{7}{12}$	269
partition wall.	1	$9\frac{3}{8}$	$\frac{3}{4}$	$9\frac{7}{12}$	67
long wall.	1	$19\frac{1}{2}$	$1\frac{1}{8}$	$9\frac{7}{12}$	210
extra thickness.	1	19	$\frac{3}{8}$	$9\frac{7}{12}$	68
side walls of passage.	2	$6\frac{7}{8}$	$1\frac{1}{8}$	$9\frac{7}{12}$	148
masonry pillar in verandah.	2	$1\frac{1}{2}$	$1\frac{1}{8}$	8	27
Latrine and bath rooms.	1	$50\frac{3}{4}$	$1\frac{1}{8}$	$9\frac{7}{12}$	547
Cross wall.	1	6	$1\frac{1}{8}$	$9\frac{7}{12}$	65
front verandah corner walls.	2	3	$1\frac{1}{8}$	$9\frac{7}{12}$	65
extra thickness.	2	3	$\frac{3}{8}$	$9\frac{7}{12}$	22
front wall.	2	4	$1\frac{1}{2}$	$9\frac{7}{12}$	115
porch.	2	2	$1\frac{1}{2}$	8	48
Total.					6545
Deductions:-					
Doors.	1	4	$1\frac{1}{2}$	7	42
- do -	9	$3\frac{1}{2}$	$1\frac{1}{2}$	$6\frac{1}{2}$	307
- do -	1	$3\frac{1}{2}$	$1\frac{1}{8}$	$6\frac{1}{2}$	26
- do -	3	$2\frac{1}{2}$	$1\frac{1}{8}$	6	51
windows.	2	$2\frac{1}{2}$	$1\frac{1}{2}$	$4\frac{1}{2}$	34
- do -	7	$3\frac{1}{2}$	$1\frac{1}{2}$	$4\frac{1}{2}$	165
- do -	1	6	$1\frac{1}{2}$	$4\frac{1}{2}$	41
- do -	2	$1\frac{1}{2}$	$1\frac{1}{2}$	4	18
- do -	1	$3\frac{1}{2}$	$1\frac{1}{8}$	$4\frac{1}{2}$	18
Ventilators.	1	4	$1\frac{1}{2}$	$1\frac{1}{2}$	9
- do -	15	$3\frac{1}{2}$	$1\frac{1}{2}$	$1\frac{1}{2}$	118
- do -	1	$3\frac{1}{2}$	$1\frac{1}{8}$	$1\frac{1}{2}$	6
- do -	2	$2\frac{1}{2}$	$1\frac{1}{8}$	$1\frac{1}{2}$	8
- do -	1	6	$1\frac{1}{2}$	$1\frac{1}{2}$	14
openings in the passage.	2	$4\frac{1}{4}$	$1\frac{1}{8}$	$6\frac{1}{4}$	60
lintals over doors in bath and latrine	3	4	$1\frac{1}{8}$	$\frac{1}{2}$	7
cills of windows in side wall of main building	1	$7\frac{1}{2}$	$1\frac{1}{2}$	$\frac{1}{2}$	6
C. O.					93

					½			
	-do-	2	4	1½	½	6		
	do Nurse	1	5	1⅛	½			
	cills and lintels of ventilators.	2	5½	1½	½	8		
	-do-	2×15	5	1½	½	113		
	-do-	1×2	5	1⅛	½	6		
	-do-	2×2	4	1⅛	½	9		
	-do-	1×2	7½	1½	½	11		
						1114		
	Burnt brick in molar arch work.							
	over doors.	1	5	1½	1½	11		
	-do-	9	4½	1½	1½	91		
	windows.	2	3½	1½	1½	16		
	-do-	7	4½	1½	1½	91		
	door	1	4½	1⅛	1⅛	6		
	window	1	4½	1⅛	1⅛	6		
	opening in the passage	2	5⅓	1⅛	1⅛	14		
	window in side wall	1	7½	1½	1½	17		
	Total deductions.					1366		
	Balance burnt brick in chunam.					5179	cft.	5179
4	Arch work. burnt brick in chunam as per above deductions.					252	cft.	252
5	Burnt stone slabs 6" thick dressed.							
	front verandah retaining wall.	1	57⅛	1⅝	(6")	93		
	" Cross wall.	1	6	1⅝	"	10		
	rear verandah. retaining wall.	1	47	1⅝	"	76		
	" passage	2	6⅜	1⅝	"	21		
	front verandah porch.	1	9	1⅝	"	15		
	cills of doors.	10	5½	2	"	110		
	-do-	1	5½	1⅝	"	9		
	-do-	3	4	1⅝	"	20		
	front steps. Centre. I step	1	14½	1¼	"	15		
	II "	1	10½	1¼	"	11		
	III "	1	6½	1¼	"	7		
	C. O.					387		

	II "		1	12	1	"	12		
	III "		1	8	1	"	8		
	rear steps.		2	3½	1	"	7		
	lintials over doors in batt room.		3	4	1⅛	"	14		
	cill of window in side wall		1	7½	1¾	"	13		
	cills of windows.		7	5	1½	"	52		
	" in front wall of verandah.		2	3	1¾	"	11		
	"		2	4	1½	"	12		
	cills and lintals of ventilators.		2	5½	1½	"	17		
	-do-		2×15	5	1½	"	225		
	-do-		1×2	5	1⅛	"	11		
	-do-		2×2	4	1⅛	"	18		
	-do-		1×2	7½	1½	"	23		
	Total burnt stone slabs.						826	Sq ft.	826
6	Cut stone circular pillars with base and capitals 8 ft. high.								
	in front verandah (full)		8	.	.	.	8		
	porch (do-)		2	.	.	.	2		
	in front verandah (half)		2×½	.	.	.	1		
	in rear verandah (full)		3	.	.	.	3		
	Total						14	No.	14
7	plastering with chunam								
	Inside above 3½ ft. Visitors room.		1	64	10½	.	672		
	general ward		1	80	10½	..	840		
	lying in ward.		1	64	10½	.	672		
	labour ward.		1	62	10½	.	651		
	gables.		6	16	16/6		256		
	nurse room in rear.		1	36¾	6 1/12		223		
	nurse and linen room.		2	34	6 1/12		414		
	bath and latrine.		2	28	6 1/12		341		
	passage		2	6⅞	6 1/12		83		
	pillars in rear verandah 3 sides.		2	3¾	4½		34		
	out side rear verandah cross walls.		3	9⅜	6 1/12		171		
	C.O.								

walls		8	2		
front wall of verandah.	2	7 1/2	4 1/2	68	
rear verandah main wall.	1	47 1/2	6 1/12	289	
out side full height passage	2	6 7/8	9 7/12	132	
bath and latrine (abroad)	1	55 1/4 47 5/8	9 7/12	456	
rear wall of nurse room.	1	12	9 7/12	115	
do — nurse and linen rooms	1	20	9 7/12	192	
Cross wall at the end	1	10 1/2	9 7/12	101	
Cross wall main building	1	19	13	247	
front verandah. Corner walls	2	3	9	54	
main wall above terrace	2	75 1/8	2 1/2	376	
front wall in front verandah.	2	4	8	64	
porch.	2	5 1/2	8	88	
Freeze - front Verandah	1	55	4	220	
do rear Total.	1	47 1/2	4	7099	
Extra.				10	
				75.27	
Deductions:—					
Doors	1	4	7	28	
do —	9	3 1/2	6 1/2	205	
do —	1	3 1/2	6 1/2	23	
do —	3	2 1/2	6	45	
Windows	2	2 1/2	4 1/2	23	
do —	7	3 1/2	4 1/2	110	
do —	1	6	4 1/2	27	
do —	2	1 1/2	4	12	
do —	1	3 1/2	4 1/2	16	
Ventilators	1	4	1 1/2	6	
do —	15	3 1/2	1 1/2	79	
do —	1	3 1/2	1 1/2	5	
do —	2	2 1/2	1 1/2	8	
do —	1	6	1 1/2	9	
Openings in the passage	2	4 1/4	6 1/4	53	
Total deductions				649	
Balance chunam plastering				63-68	sqs 63-68
				68.78	68.78

	Side wall.	1	40	.	$1\frac{1}{2}$	60			
	rear side alround.	1	131	.	$1\frac{1}{2}$	197			
	Total					372	sqrs	3·72	
9	White and Colour washing 2 Coats as per plastering and painting						sqrs	~~67·10~~	
10	Chunam plastering with $\frac{1}{8}$" thick cement plastering.							72·50	
	Inside. bath and latrine alround.	2	28	..	$3\frac{1}{2}$	196			
	nurse, room at the end.	1	$36\frac{3}{4}$	.	$3\frac{1}{2}$	129			
	linen and nurse rooms.	2	34	.	$3\frac{1}{2}$	238			
	passage	2	8	.	$3\frac{1}{2}$	56			
	Cross walls rear verandah.	3	$9\frac{3}{8}$	.	$3\frac{1}{2}$	98			
	main wall in rear.	1	$47\frac{1}{2}$	.	$3\frac{1}{2}$	166			
	labour ward.	1	62	.	$3\frac{1}{2}$	217			
	lying in ward.	1	64	.	$3\frac{1}{2}$	224			
	general ward.	1	80	.	$3\frac{1}{2}$	280			
	Visitors room.	1	64	.	$3\frac{1}{2}$	224			
	front verandah main wall.	1	$75\frac{1}{8}$	.	$3\frac{1}{2}$	263			
	front wall of verandah.	2	$7\frac{1}{2}$	.	$3\frac{1}{2}$	53			
	Corner walls	2	$1\frac{7}{8}$	.	$3\frac{1}{2}$	13			
	Total Chunam plastering with cement.					2157	sqrs	21·57	
11	Oil painting over cement plastering. as per above.						sqrs	21·57	
12	Flooring with ~~Marshels~~ Marseilles tiles over 3" Concrete bed. ~~pointed with cement~~								
	Visitors room.	1	16	16	.	256			
	General ward.	1	24	16	.	384			
	Lying in ward.	1	16	16	.	256			
	labour ward.	1	16	15	.	240			
	Sofits of doors.	8	4	1	.	32			
	Total					1168			
	Deduct old bits available.					135			
	balance					1033	sqrs	10·33	
13	Flooring with old Marshels tiles on 3" Concrete bed.								
	As per above deductions.					135	sqrs	1·35	
14	Flooring with Caddapa slabs on 3" Concrete bed.								
	Front verandah.	1	$75\frac{1}{8}$	$8\frac{1}{8}$	.	610			

	Total.					106	sqft	106
21	Teak wood wrought and put up.							
	Couples 2 ft from centre to centre.	2×34	13.65 13 1/4	3"	5"	93.9		
	Collers big.	34	12	3"	5"	42.5		
	do — small.	34	6	3"	5"	21.3		
	rafter at the hip.	1	13.05 18 1/4	3"	5"	1.4		
	Wall plate for the rafters.	2	75 1/8	3"	4"	12.5		
	-do-	1	19	3"	4"	1.6		
	Wall plate for joists	~~2×2~~	75 1/8	3"	4"	25.00 ~~12.5~~		
	~~wall plate on rear wall~~	~~1~~	~~9 1/2~~	~~3"~~	~~4"~~	~~1.2~~		
	~~-do-~~	~~1~~	~~17~~	~~3"~~	~~4"~~	~~1.4~~		
	wall plate on bath and latrine.	2	17 1/2	3"	4"	2.9		
	hip rafters	2	17 1/2	4"	6"	5.8		
	jack rafters	4×4	6 1/2	3"	5"	10.8		
	Teak wood joists for front verandah. @ 15" @	61	10 1/2	3"	7"	93.4		
	nurse room.	8	11 1/2	3"	7"	13.4		
	linen and nurse room.	2×7	11 1/2	3"	7"	23.5		
	Verandah.	39	11 1/2	3"	7"	65.4		
	passage.	7	8 1/2	3"	7"	8.7 ~~3.6~~		
	bath and latrine rooms.	2×7	7'	3"	5"	10.2		
	Total.					~~422.4~~ 444-3	cft	~~422.4~~ 444-3
22	Bressummers. Steel girders 6"×12" with painting.					432.3		432.30
	front verandah.	1	78 3/4	.	.	78 3/4		
	side.	1	8 3/4	.	.	8 3/4		
	porch.	1	10.	.	.	10		
	rear verandah.	1	48 1/2	.	.	48 1/2		
	Total @ 44# per ft					146	cwt	57.24
23	Roofing with I class Mangalore Tiles on teak rafters.							
	front and rear.	2	$\frac{78\frac{1}{8}+67\frac{1}{8}}{2}$		13 1/4	1924		
	side.	1	$\frac{22+0}{2}$		13 1/4	146		
	Total.					2070	sqrs	20.70

	rear verandah including rooms	1	76	$11\frac{1}{4}$	.	855		
	passage.	1	8	$8\frac{1}{2}$	.	68		
	bath and latrine.	1	18	7	.	126		
	Porch —	1	10	$1\frac{1}{2}$		15		
	Total.					1828	sqrs	18.28
25	Mangalore ridge tiles set in mortar.							
	ridge	1	$67\frac{1}{8}$	.	.	67		
	on hips	2	$16\frac{1}{2}$	.	.	33		
	Total					100	rft.	100
26	Eave board ornamental 12"							
	front	2	$78\frac{1}{8}$	.	.	156		
	sides	1	22	.	.	22		
	Total.					178	rft.	178
27	Cornice 12" thick with string course.							
	front verandah. front	1	$76\frac{1}{4}$	.	.	76		
	side.	1	10	.	.	10		
	porch.	2	3	.	.	6		
	rear verandah.	1	27	.	.	27		
	"	1	42	.	.	42		
	side.	1	11	.	.	11		
	above passage.	2	$6\frac{7}{8}$	.	.	14		
	bath and latrine around.	1	45	.	.	45		
	Total					231	rft.	231.
28	Burnt brick ornamental parapet wall over roof. with plastering, Coping, etc. complete				$(1\frac{1}{2}' \times 1\frac{1}{8}')$			
	Front verandah. front.	1	$75\frac{3}{4}$	.	$(1\frac{1}{2}')$	76		
	side.	1	$8\frac{3}{8}$	.	"	8		
	porch.	2	3	.	"	6		
	rear verandah.	1	$28\frac{1}{8}$	.	"	28		
		1	$43\frac{1}{8}$	.	"	43		
	side	1	$9\frac{3}{8}$	.	"	9		
	above passage	2	$6\frac{7}{8}$	.	"	14		
	above bath and latrine around.	1	$42\frac{1}{2}$	.	"	43		
	Total.							

		1	$13\frac{1}{4}$	$1\frac{1}{12}$		14		
	collers big	34	12	$1\frac{1}{12}$		442		
	" small.	34	6	$1\frac{1}{12}$		221		
	joists	61	$10\frac{1}{2}$	$1\frac{5}{12}$		907 ~~865~~		
	"	8	11	$1\frac{5}{12}$		125		
	"	2×7	11	$1\frac{5}{12}$		218		
	"	39	11	$1\frac{5}{12}$		608		
	"	7	8	$1\frac{5}{12}$		79		
	hip rafters	2	$17\frac{1}{2}$	$1\frac{1}{3}$		47		
	jack rafters	4×4	$6\frac{1}{2}$	$1\frac{1}{12}$		113 84		
	Lattice Total.	247	6	1		~~3707~~ 3750	sqs	~~3707~~ 37.50
30	Burnt brick ornamental parapet wall in verandah complete (9" × $2\frac{1}{2}$ H.)							
	front between pillars.	6	$7\frac{1}{6}$			43		
	side "	1	4			4		
	Total					47	rft.	47
31	Concrete drain alround complete	1	240			240	rft.	240
32	Silicate painting							
	doors.	1×2	4		7	56		
	-do-	10×2	$3\frac{1}{2}$		$6\frac{1}{2}$	465		
	-do-	3×2	$2\frac{1}{2}$		6	90		
	windows.	~~SK~~ 2×~~2~~ 3	$2\frac{1}{2}$		$4\frac{1}{2}$	45		
	-do-	~~SK~~ 7×~~2~~ 3	$3\frac{1}{2}$		$4\frac{1}{2}$	220		
	-do-	~~SK~~ 1×~~2~~ 3	6		$4\frac{1}{2}$	54		
	-do-	~~SK~~ 2×~~2~~ 3	$1\frac{1}{2}$		4	24		
	Ventilators	1×2	4		$1\frac{1}{2}$	12		
	-do-	2×17	$3\frac{1}{2}$		$1\frac{1}{2}$	178		
	-do-	2×2	$2\frac{1}{2}$		$1\frac{1}{2}$	15		
	-do-	1×2	6		$1\frac{1}{2}$	18		
	Total.					1167	sqs	11.67
33	Clearing site, levelling ground, and barring wood work.					L.S. rupees.		25/-

	as per plan. Cutting grooves & mortar	2 S. rupees					100/-
35	Providing new teak wood finial (big)	1			1	No	1
36	Teak wood pendents.	2			2	"	2
37	Inscription of name				2 S.R.		10/-

Washmiaeing
19-1-28

Executive Engineer
Delhi Division

OK
18-1-28

S.No.	Items of work.	per	Rate			Quantity	Cost.
1	Earthwork excavation. and following viz —	c.yd	0	4	.	240	60
2	Burnt stone in mortar	c.ft.	0	4	6	~~7247~~ 7322	~~2038~~ 2059
3	Burnt brick in mortar.	c.ft.	0	4	6	5179	1457
4	Archwork burnt brick in mortar.	c.ft.	0	6	.	25·2	9s
5	Burnt stone slab 6" thick dressed.	sq.ft.	0	6	.	826	310
6	Cut stone circular pillars with base and capitals	No.	18	.	.	14	252
7	plastering with Chunam	sqr	3	8	.	~~6268~~ 68·78	~~223~~ 241
8	Pointing with Chunam	"	2	8	.	3·72	9
9	White and Colour washing 2 coats	"	0	5	.	~~67·50~~ 72·50	21
10	Chunam plastering with $\frac{1}{8}$" thick cement plastering	"	12	.	.	21·57	259
11	Oil painting	"	8	.	.	21·57	173
12	Flooring with new Marshellos tiles over 3" concrete bed and cement pointing etc. complete.	"	75	.	.	10·33	776
13	Flooring with old Marshello tiles over 3" concrete bed and cement pointing.	"	18	.	.	1·35	24
14	Flooring with new Caddapa slabs over 3" Concrete bed and cement pointing.	"	40	.	.	13·70	548
15	Flooring with old Caddapa slabs over 3" Concrete bed and cement pointing.	"	15	.	.	0·60	9
16	Teakwood pannelled doors with hooks, hinges etc complete	sq.ft.	2	12	.	256	704
17	Teakwood battened doors old with necessary repairs. (3 doors)	L.S. rupees					15
18	Teakwood pannelled windows with glazed shutters iron bars, hinges etc. Complete.	sq.ft.	4	.	.	172	688
19	Fixing teakwood old windows with necessary repairs	No.	2	.	.	1	2
20	Teakwood ventilators with glazed shutters, iron bars, hinges etc. complete.	sq.ft.	2	.	.	106	212
21	Teakwood wrought and put up.	c.ft.	8	.	.	~~4004~~ ~~4443~~ 4323	~~3379~~ ~~3557~~ 3468
22	Steel girders 6"×12" with painting.	cwt	16	.	.	57·4	918
23	Roofing with I class Mangalore tiles on teak reepers and flat tiles (reepers 6" apart)	sqr	50	.	.	20·70	1035
24	Roofing with pucca terrace 9" thick.	"	45	.	.	18·28	823
25	Mangalore ridge tiles set in mortar.	r.ft.	0	8	.	100	50
26	Teakwood eave board 12"×1" as per designs.	r.ft.	1	.	.	178	178
		C.O					14432

27	Cornice 12" thick with string course.	rft.	1	.	.	231	231
28	Burnt brick in mortar ornamental parapet wall over the roof with plastering etc. Complete as per design	rft.	1	8	.	227	340
29	Chacolate painting.	sqr	5	.	.	37·50	187
30	Burnt brick ornamental parapet wall in verandah with coping, plastering etc. as per design.	rft.	1	8	.	47	70
31	Concrete drain alround.	rft.	0	10	.	240	150
32	Silicate painting.	sqr	6	.	.	11·67	70
33	Clearing site, levelling ground and carving woodwork	L.S.					25
34	Ornamental work in front porch as per plan.	L.S.					100
35	Providing new teak wood finials	Nos	1	8	.	1	2
36	Providing new teak wood pendents	-	1	4	.	2	3
	Mouldings of frame.						10
	Total					15628	15608
	Contingencies @ 5% nearly					607	780
	Grand total.						16230

3-3-25

Executive Engineer,
Solar Division.

18.1.25

S.No.	Details of work.	No.	Dimensions.			Contents	Total.
	Dismantling the masonry and removing debry						
	Basement store rooms longitudinal walls.	1	$18\frac{1}{2}$	2	1	37	
	side wall.	2	$8\frac{3}{4}$	2	1	35	
	Superstructure. longitudinal walls.	1	18	$1\frac{1}{2}$	$6\frac{3}{4}$	182	
	side walls.	2	9	$1\frac{1}{2}$	$\frac{12\frac{1}{4}+6\frac{3}{4}}{2}$	256	
	passage to bath, side walls.	2×2	5	$1\frac{1}{2}$	1	30	
	pillars Square.	2×2	$1\frac{2}{3}$	$1\frac{2}{3}$	$7\frac{1}{4}$	81	
	Honey Comb work.	2×2	6	$5/6$	5'	100	
	passage to latrine and bath longl. walls	2	$10\frac{1}{3}$	$5/6$	5'	86	
	honey comb work.	2	$8\frac{5}{6}$	$5/6$	5'	73	
	-do-	2	$8\frac{5}{6}$	$5/6$	5'	32	
	latrine and bath longl. walls	2	$16\frac{1}{2}$	$1\frac{1}{2}$	12	594	
	-do-	2	$16\frac{1}{2}$	$1\frac{1}{2}$	8	396	
	-do- side walls.	3×2	6	$1\frac{1}{2}$	$\frac{12+8}{2}$	540	
	godown behind latrine. longl. walls.	2	9	$1\frac{1}{2}$	8	216	
	side walls.	2×2	6	$1\frac{1}{2}$	$\frac{12+8}{2}$	360	
	Opening out a portion of wall between rooms of wards for inserting door frames.	2	$4\frac{1}{4}$	$1\frac{1}{2}$	$7\frac{1}{3}$	95'	
	door	2×2	$2\frac{1}{2}$	$1\frac{1}{2}$	6	90	
	"	2	$2\frac{1}{2}$	$1\frac{1}{2}$	$5\frac{1}{2}$	41	
	-do-	1	$3\frac{1}{2}$	$1\frac{1}{2}$	$6\frac{1}{2}$	34	
	windows	1	$3\frac{1}{2}$	$1\frac{1}{2}$	$4\frac{1}{2}$	24	
	vacant space in honey comb work.	2×2	$5\frac{1}{2}$	1	6	132	
	pillars in front.	4	$1\frac{3}{4}$	$1\frac{3}{4}$	6	74	
	Side walls.	2	$9\frac{1}{2}$	$1\frac{1}{2}$	8	228	
	wall for shifting the door.	2	$4\frac{1}{2}$	$1\frac{1}{2}$	8	108	
	removing the side window.	1	$6\frac{1}{2}$	$1\frac{1}{2}$	$5\frac{1}{2}$	54	
	removing circular ventilators for and inserting rectangular ventilators.	1	$6\frac{1}{2}$	$1\frac{1}{2}$	2	40	
	Total.					3938	cft. 3938
	Dismantling Bengal terrace.						
	over the rear passage.	2	$9\frac{3}{4}$	10	.	195	
	tiled roof, way to latrine	2	14	$6\frac{1}{4}$	.	175	

C.O.

	godowns behind.	2	11	11	.	242			
	Store rooms.	1	20	11	.	220			
	Existing roof of ward.	2	62 1/2	13 1/2	.	1687			
	Bengal terrace over front verandah	1	62 1/2	11	.	687			
	Total					3580	sqrs	35·80	
3	Removing the couples of the main building and refixing the same after the walls are raised.			L.S. Rupees.					120/-
4	Removing the Cuddapa slabs.	2	8	6	.	96			
		2	8	3	.	48			
		2	10 1/2	3	.	63			
		2	6	6	.	72			
	Total					279	sqrs	2·79	
5	Removing Marbles flooring tiles.								
	Store rooms.	1	15	9	.	135	sqrs	1·35	
6	Additions to the present building.								
b	Earthwork excavation. Rear verandah.	1	59 1/8	2 5/8	5'	776			
	Cross walls.	2	7 7/8	2 5/8	5'	207			
	passage	2	5 3/8	2 5/8	5'	141			
	latrine and bath rooms.	1	50 3/4	2 5/8	5'	~~333~~ 666			
	Steps rear.	1	4	2 1/4	1/2	5'			
	do — front	1	12	2 1/2	1/2	16			
	Total					~~1478~~ 1811	sqd	67 6·5	
	Burnt stone in mortar.								
	Foundations I step. Rear verandah.	1	59 1/8	2 5/8	2 1/2	388			
	Cross walls.	2	7 7/8	2 5/8	2 1/2	103			
	passage	2	5 3/8	2 5/8	2 1/2	71			
	latrine and bath rooms.	1	50 3/4	2 5/8	2 1/2	~~166~~ 333			
	Steps.	1	4	2 1/4	1/2	5'			
	II step. Rear verandah.	1	59 1/8	2 1/8	2 1/2	314			
	Cross walls.	2	8 3/8	2 1/8	2 1/2	89			
	passage	2	5 7/8	2 1/8	2 1/2	62			
	bath and latrine.	1	50 3/4	2 1/8	2 1/2	270			
	Basement. Rear verandah.	1	59 1/8	1 5/8	1 1/2	144			
	Cross walls.	2	8 7/8	1 5/8	1 1/2	43			
	passage	2	6 3/8	1 5/8	1 1/2	31			

II "	1	10	2	½	10
III "	1	8	1	½	4
Steps rear.	1	3½	2	¾	5
extra thickness at the corners of front verandah	2	3	⅜	1½	3
Total					1850
					2017
Deductions:-					
Slabs on the retaining wall.	1	47	1 5/8	½	38
cills of doors.	1	5	1 5/8	½	4
-do-	3	4	1 5/8	½	10
Steps front I	1	16	1	½	8
II	1	12	1	½	6
III	1	8	1	½	4
steps rear	2	3½	1	½	4
Total					74
Balance burnt stone in chunam.					1943 1776
Burnt brick in mortar.					
Superstructure. Lines rooms in rear. long. wall	1	12	1⅛	9 7/12	129
" Cross walls	2	9 3/8	1⅛	9 7/12	202
Side walls of passage	2	6 7/8	1⅛	9 7/12	148
pillars in verandah.	2	1½	1⅛	8	27
latrines and bath rooms	1	5 3/4	1⅛	9 7/12	54
raising the existing walls of the wards by 1 ft. and ½ ft. of old wall while removing the couples	2	61	1½	1½	275
raising gables	2×3	9½	1½	1½	128
closing the openings of the door ways.	2	4½	1½	7	94
-do- window.	1	3½	1½	4½	24
wall at the corner of the front verandah.	2	3	1⅛	8	54
extra thickness -do-	2	3	⅜	8	18
Extra here and there while dismantling	2	S.			50
					1708
					137
Raising Pillars front Total.	1	61	1⅛	2	1696
rear	1	48	1⅛	2	1941
Deductions:-					
door lines room.	1	3½	1⅛	6½	26
windows	1	3½	1⅛	4½	17
doors in bath and latrine.	3	2½	1⅛	6	51
ventilators.	2	2½	1⅛	1½	8
					102

	opening in the passage walls.	2	4 1/4	1 1/8	6 1/4	60			
	cills and lintals of ventilators.	2×2	4	1 1/8	1/2	9			
	— do —	1×2	5	1 1/8	1/2	6			
	cills of windows.	1	5	1 1/8	1/2	3			
	Archwork over passage	2	5 1/2	1 1/8	1 1/8	14			
	" over windows.	1	4 1/2	1 1/8	1 1/8	6			
	Total.					206			
	Balance burnt brick in mortar.					~~1490~~	cft.	~~1490~~ 1735	
9	Burnt stone slabs 6" thick dressed.								
	Slab over retaining wall.	1	47	1 5/8	6"	76			
	cill slab of door.	1	5	1 5/8	"	8			
	— do —	3	4	1 5/8	"	20			
	cills and lintals of ventilators.	2×2	4	1 1/8	"	18			
	— do —	1×2	5	1 1/2	"	15			
	cill slab of window	1	7	1 3/4	"	12			
	cills and lintles of ventilators (big)	2	7	1 1/2	"	21			
	lintles of doors.	3	4	1 1/8	"	14			
	steps front I step.	1	16	1	"	16			
	II "	1	12	1	"	12			
	III "	1	8	1	"	8			
	" rear	2	3 1/2	1	"	7			
	Total.					227			
	Deduct old stone slabs got by dismantling.					50			
	balance new stone slabs.					177	sqft.	177	
10	Resetting old stone slabs in mortar as per deductions.					50	sqft.	60	
11	Archwork. burnt brick in mortar.								
	over old doors (shifted)	2	4 1/2	1 1/2	1 1/2	20			
	over door	1	4 1/2	1 1/8	1 1/8	6			
	over window.	1	4 1/2	1 1/8	1 1/8	6			
	— do —	1	7 1/2	1 1/2	1 1/2	17			
	over openings in the passage	2	5 1/2	1 1/8	1 1/8	14			
	Total.					63	cft.	63	
12	Repairing and refixing the old doors	5	.	.	.	5	No.	5	
13	Repairing and refixing the old windows.	2	.	.	.	2	No.	2	

	iron bars etc. complete.	2	$2\frac{1}{2}$	.	$1\frac{1}{2}$	8			
	—do—	1	6	..	$1\frac{1}{2}$	9			
	Total					17	sqft.	17	
16	Teakwood windows with iron bars, etc.	1	6	.	$4\frac{1}{2}$	27	"	27	
17	Circular pillars with base and capitals 8 ft. high.								
	in front verandah. (full)	8	.	.	.	8			
	do — (half)	$2\times\frac{1}{2}$	.	.	.	1			
	rear verandah. (full)	3	.	.	.	3			
	Total					12	Nos	12	
18	plastering with chunam								
	above $3\frac{1}{2}$ ft. linen room in rear verandah.	1	$36\frac{3}{4}$	$6\frac{1}{12}$	.	224			
	pillars in verandah (full height)	2	$3\frac{3}{4}$	8	.	60			
	passage.	2	$6\frac{7}{8}$	$6\frac{1}{12}$	.	83			
	bath and latrine.	2	28	$6\frac{1}{12}$	.	341			
	outside of linen room.	1	$9\frac{3}{8}$	$6\frac{1}{12}$	.	57			
	outside rear wall —do—	1	12	$9\frac{7}{12}$	.	115			
	side wall —do—	1	$10\frac{1}{2}$	$9\frac{7}{12}$	.	101			
	out side wall of bath and latrine.	1	$45\frac{7}{8}$	$9\frac{7}{12}$	.	440			
	portion wall newly raised.	2×2	61	2	.	488			
	gable	2×2×3	10	$1\frac{1}{2}$	.	180			
	passage	2	$6\frac{7}{8}$	$9\frac{7}{12}$	.	132			
	portion of door way closed.	2×2	4	7	.	112			
	—do— window do.	2	$3\frac{1}{2}$	$4\frac{1}{2}$	.	32			
	patches here and there	1	61	-	4	244			
	Total	1	48		4	192			
						2911			
	Deductions:-								
	doors in bath and latrine.	3	$2\frac{1}{2}$	.	6	45			
	do.	1	$3\frac{1}{2}$	.	$6\frac{1}{2}$	23			
	windows	2	$3\frac{1}{2}$	.	$4\frac{1}{2}$	32			
	Ventilators.	2	$2\frac{1}{2}$	.	$1\frac{1}{2}$	8			
	passage.	2	$4\frac{1}{4}$	.	$6\frac{1}{4}$	53			
	Total.					161			
	Balance plastering with chunam					2750	sqrs	27.50	
19	Pointing with chunam					27.50		27.50	
	basement around in rear.	1	122	.	$1\frac{1}{2}$	183	sqrs	1.83	

21	Plastering with Chunam with $\frac{1}{8}$" cement plastering					29.33		29.33.
	Linen room.	1	$36\frac{3}{4}$	.	$3\frac{1}{2}$	129		
	out side wall.	1	$9\frac{3}{8}$	.	$3\frac{1}{2}$	33		
	bath and latrine.	2	28	.	$3\frac{1}{2}$	196		
	passage.	2	8	.	$3\frac{1}{2}$	56		
	Total					414	sqrs	4.14
22	Oil painting as per cement plastering					414	"	4.14
23	Flooring with Caddapa slabs over 3" Concrete bed							
	bath and latrine.	2	8	6	.	96		
	passage	1	$6\frac{5}{8}$	$7\frac{1}{2}$	.	50		
	rear verandah.	1	48	$9\frac{1}{8}$	.	438		
	linen room in rear verandah.	1	9	$9\frac{3}{8}$	.	84		
	Total					668		
	Deduct the slabs available from dismantling the building after deducting $\frac{1}{4}$ for wastage and 60 sqft. for new building		$(\frac{3}{4}\times\frac{279}{1}-60)$			150		
	Balance new Caddapa slab flooring					518	sqrs	5.18
24	Refixing the old Caddapa slabs on 3" Concrete bed and cement pointing.					150	sqrs	1.50
25	Teakwood wrought and put up.							
	Hip rafters	2	$17\frac{1}{2}$	4"	6"	5.8		
	jack rafters	4×4	$6\frac{1}{2}$	3"	5"	10.8		
	wall plate for the terrace main building	2	60	2"	4"	10.0		
	" bath and latrine.	2	$17\frac{1}{2}$	3"	4"	2.9		
	" rear wall of linen room	1	$9\frac{1}{2}$	3"	4"	0.8		
	joists for rear verandah.	39	$11\frac{1}{2}$	3"	7"	65.4		
	linen room.	8	$11\frac{1}{2}$	3"	7"	13.4		
	passage.	7	$8\frac{1}{2}$	3"	7"	8.7		
	bath and latrine.	2×7	7	3"	5"	10.2		
	front verandah.	49	$10\frac{1}{2}$	3"	7"	75.0		
	Total					203.0	cft.	203.0
26	Breeze summers or Steel girders 6"×12"							
	front verandah.	1	60	.	.	60		
	side	1	$8\frac{3}{4}$	.	.	$8\frac{3}{4}$		
	rear verandah.	1	$47\frac{1}{2}$					

		1	$\frac{22+0}{2}$	-	$13\frac{1}{4}$	146		
	Total.					1656	sqrs	16.56
28	Roofing with pacca terrace 9" thick.							
	front verandah.	1	$60\frac{1}{2}$	$10\frac{1}{2}$	.	620		
	rear verandah including rooms	1	58	$11\frac{1}{4}$	.	652		
	passage.	1	8	$8\frac{1}{2}$	.	68		
	bath and latrine.	1	18	7	.	126		
	Total					1466	sqrs	14.66
29	Mangalore Ridge tiles set in mortar.							
	main ridge	1	$51\frac{1}{2}$	.	.	52		
	hips.	2	$17\frac{1}{2}$	.	.	35		
	Total					87	rft.	87
30	Teak wood eave board							
	front and rear.	2	$62\frac{1}{2}$	.	.	125		
	side	1	22	.	.	22		
	Total					157	rft.	157
						147		147
31	Cornice 12" thick with string course.							
	front verandah. front	1	61	.	.	61		
	side	1	10	.	.	10		
	rear verandah.	1	22	.	.	22		
	"	1	27	.	.	27		
	side	1	11	.	.	11		
	above passage.	2	$6\frac{7}{8}$	.	.	14		
	bath and latrine around.	1	45	.	.	45		
	Total					190	rft.	190
32	Burnt brick ornamental parapet wall over the roof as per designs.							
	front verandah.	1	61	.	.	61		
	side.	1	$8\frac{3}{4}$	.	.	$8\frac{3}{4}$		
	rear verandah.	1	$28\frac{1}{8}$	.	.	28		
	"	1	$23\frac{1}{8}$	.	.	23		
	passage	2	$6\frac{7}{8}$	.	.	14		
	bath and latrine.	1	$42\frac{1}{2}$	.	.	43		
	Total					187	rft.	187
						177		177
33	Chacolate painting to woodwork.							
	rafters	2×26	$13\frac{1}{4}$	$1\frac{1}{12}$	.	746		
		1	$13\frac{1}{4}$	$1\frac{1}{12}$	.	14		
	collers (big)	26	12	$1\frac{1}{12}$	.	338		

	Collers (small)	26	6	$1\frac{1}{12}$	.	169			
	hip rafters	2	$17\frac{1}{2}$	$1\frac{1}{3}$	.	47			
	jack rafters	4x4	$6\frac{1}{2}$	$1\frac{1}{12}$	.	113			
	joists front verandah.	49	$10\frac{1}{2}$	$1\frac{5}{12}$	.	729			
	" rear verandah.	39	$11\frac{1}{2}$	$1\frac{5}{12}$	.	635			
	linen room.	8	$11\frac{1}{2}$	$1\frac{5}{12}$	.	130			
	passage	7	$8\frac{1}{2}$	$1\frac{5}{12}$	.	84			
	bath and latrine.	2x7	7	$1\frac{1}{12}$	.	106			
	Total.					3111.	qrs	31·11	
34	Silicate painting to doors and windows etc.								
	doors old and new.	9x2	$3\frac{1}{2}$	$6\frac{1}{2}$	.	409			
	" do-	2x3	$2\frac{1}{2}$	6	.	90			
	windows	2x7	$3\frac{1}{2}$	$4\frac{1}{2}$	.	220			
	do-	1x2	6	$4\frac{1}{2}$	.	54			
	Ventilators.	2x1	$2\frac{1}{2}$	$1\frac{1}{2}$	.	8			
	do-	8	$3\frac{1}{2}$	$1\frac{1}{2}$	.	42			
	do-	1	6	$1\frac{1}{2}$	.	9			
	Total.					832	qrs	8·32	
35	Burnt brick ornamental parapet wall including coping, plastering, colour and white washing etc. Complete								
	in front verandah front	6	$7\frac{1}{6}$	.	.	43			
	side	1	4	.	.	4			
	Total					47	rft.	47	
36	Providing new teak wood finials.	1	.	.	.	1	Nos	1	
37	Providing new teak wood pendents	2	.	.	.	2	"	2	

No.	Items of work.	Per	Rate	Quantity	Cost
1	Dismantling the masonry and removing the debry.	cft.	0 0 6	3938	123
2	Dismantling the roofing, Bengal terrace etc.	sqr	3 . .	35.80	107
3	Removing the Cupples and refining the same with any repairs if necessary after the walls are raised.	L.S.	rupees		120/-
4	Removing the Caddapa slabs	sqrs	2 . .	2.79	6
5	Removing Marshello flooring tiles.	"	3 . .	1.35	4
6	Earthwork excavation.	cyd	0 4 .	~~5.0~~ 67	~~11~~ 17
7	Burnt stone in mortar.	cft.	0 4 6	~~1776~~ 1943	~~500~~ 546
8	Burnt brick in mortar.	cft.	0 4 6	~~1440~~ 1735	~~419~~ 488
9	Burnt stone slabs 6" thick dressed (new)	sqft.	0 6 .	177	66
10	Resetting old burnt stone slabs in chunam	"	0 2 .	50	6
11	Archwork burnt brick in mortar.	cft.	0 6 .	63	24
12	Repairing and refixing the old doors.	each.	1 8	5	8
13	Repairing and refixing the old windows.	"	1 . .	2	2
14	Teak wood new pannelled doors with hooks, hinges, etc.	sq ft.	2 12 .	68	187
15	Teak wood ventilators with glazed shutters, iron bars etc. complete.	sqft.	2 . .	17	34
16	Teak wood windows with iron bars etc. complete as per designs in the plans.	sqft.	3 . .	27	81
17	Circular pillars with base and capitals.	each	18 . .	12	216
18	plastering with chunam.	sqrs	3 8 .	~~23.04~~ 27.50	~~81~~ 97
19	Pointing with chunam.	"	2 8 .	1.83	5
20	White and colour washing.	"	0 5 .	~~21.87~~ 29.33	8
21	plastering with chunam with $\frac{1}{8}$" thick cement plastering.	"	12 . .	4.14	50
22	Oil painting.	"	8 . .	4.14	33
23	Flooring with new Caddapa slabs over 3" Concrete bed and cement pointing.	"	40 . .	5.18	207
24	Refixing the old Caddapa slabs over 3" Concrete bed and cement pointing.	"	15 . .	1.50	23
25	Teak wood wrought and put up.	cft.	8 . .	203.0	1624
26	Steel girders of 6"×12" with paintingetc. complete.	cwt	16 . .	45.6	730
27	Roofing with I class Mangalore tiles on teak reepers and flat tiles the reapers being 6" apart.	sqr	50 . .	16.66	828
28	Roofing with pucca terrace 9" thick.	"	40 . .	14.66	660
					6166

C. O.

6300 6215

							6166
	B.F.						6300
29	Mangalore Ridge tiles set in mortar.	rft.	0	8	.	87	43
30	Cornice 12" thick with string course.	"	1	.	.	190	190
31	Teak wood cave board 12"x1"	"	1	.	.	~~157~~ 147	157 147
32	Burnt brick ornamental parapet wall over the roof as per design with plastering etc. complete	rft.	1	8	.	177 187	265 280
33	Chocolate painting.	sqr	5	.	.	31·11	156
34	Silicali painting	"	6	.	.	8·32	50
36	Burnt brick ornamental parapet wall including coping, plastering etc. complete as per design.	rft.	1	8	.	47	70
36	Providing teakwood finials.	No.	1	8	.	1	2
37	Providing teakwood pendents	No.	1	4	.	2	3
	Total					7226	~~7141~~ 7117
	Contingencies @ 5% nearly.					244	~~298~~ 353
	Grand total.						7470/-

Checked

3-3-28

Executive Engineer
Zolar Division

18-1-28

General Abstract

Items of work.	Amount.	
Extending the ward of the Civil Hospital.	16230 ~~16,390~~	
Improving the ward of the Civil Hospital.	7470 / 23700	
Deduct cost of old materials got by auction	-100	23600 ~~23,760/-~~
Net amount of estimate		

Checked T. Tab. 20-2-28.

3-3-28

80

18.1.25

Executive Engineer
Kolar Division.

Site Plan of the Civil Hos of Kolar

Scale = 20 : 1"



spital


Female dressing Room
Examination Room
Prescribing Room
Store Room
Compounding Room
Sanitary Room
Office Room
Clerks Room
Railway Feeder Road

REFERENCE TABLE

DISMANTLING "

PROPOSAL

BLACK DENOTES EXISTING



Traced
by
J. Sambandamurthy
S.O



Approved by
the Commissioner
on 3.12.26
at Kolar

Executive Engineer, 19.1.26
Kolar Division.

18.1.26

Executive Engineer,
Kolar Division.

29/1/1926

In all future correspondence please quote this
No. A.S.C. 1196/28-29.
Encls. 2

OFFICE OF THE DEPUTY COMMISSIONER,
KOLAR DISTRICT.

Dated, Kolar, the 27th November *19* 29.

FROM

A. V. RAMANATHAN, ESQ., B.A.,
Deputy Commissioner,
Kolar District.

GENERAL MISCELLANEOUS BRANCH
3289
30 NOV. 1929

To R. Ranga Rao, Esq., B.A., B.L.,
Chief SECRETARY TO GOVERNMENT OF MYSORE,
Department,
Bangalore.

CHIEF SECRETARY'S OFFICE
30 NOV. 1929

RR 30/11/29.

SIR,

Improvements - District Hospital - Kolar.

With reference to your letter No. G. 13956-7/Med. 49-25 dated 17-5-1929 enquiring whether the Municipal Council, Kolar, are willing to contribute towards the cost of the improvements to the District Hospital at Kolar, I have the honour to forward herewith the Kolar Town Municipal President's letter No. 272/29-30 dated 15-11-29 together with the resolution of the Council pleading inability to contribute on account of the strained finances of the Council inasmuch as they had paid their quota of contribution -- towards the cost of the Female Dispensary building which was purchased by them.

Copy

I have the honour to be,

S i r,

Your most obedient Servant,

Treasury Assistant Commissioner,
For Deputy Commissioner,
Kolar District.
(absent from Head-quarters)

SRS.

28/11

TOWN MUNICIPAL COUNCIL,

No. 272 Summary

Dated, Kolar, the 12th November 1929;

FROM

M. ABDUS SUBHAN ESQ.,
PRESIDENT,
TOWN MUNICIPAL COUNCIL,
KOLAR.

To

A. V. Ramanathan Esquire, B.A.,
Deputy Commissioner, Kolar District,
Kolar.



Sir,

With reference to your Memo No. A.5. ~~1222~~ 1196 of 28-29 dated 23rd May 1929 forwarding a copy of letter No. G.13956 -7/Med. 49-25 dated 17th May 1929 from the Chief Secretary to the Government of Mysore enquiring whether this Municipal Council are willing to contribute towards the cost of the improvements to the District Hospital at Kolar, I have the honour to state that the subject was placed before the ~~xxxxxxxxxxxx~~ council for their opinion.

2. The Council considered the matter at their meeting held on ~~2~~7-10-1929 and resolved that they cannot bear this contribution in their present financial condition. They further resolved that they had paid their quota of contribution towards the cost of Female Dispensary ~~xxxxxx~~ Building which was purchased by them.

3. A copy of the resolution of the Council is herein enclosed for reference.

I have the honour to be,
Sir,
Your most obedient servant

President,
Town Municipal Council, Kolar.

15/11/29

ಶ್ರೀ 1929ನೇ ಇಸವಿ ಡಿಸೆಂಬರ್ ತಿಂಗಳ 7ನೇ ತಾರೀಖಿನಂದು ಮಧ್ಯಾಹ್ನ 3-30 ಘಂಟೆಗೆ ಕೂಡಿದ ಸಭೆಯಲ್ಲಿ ಮಾನ್ಯ ಸದಸ್ಯರುಗಳು ಹಾಜರಿದ್ದರು.

Subject 3. ಕೋಲಾರ ಪಟ್ಟಣಕ್ಕೆ ಇಂಪ್ರೂವ್‌ಮೆಂಟ್ ಸ್ಕೀಮ್ ಮಾಡಿ ಅದನ್ನು ಜಾರಿಗೆ ತರುವ ವಿಷಯದಲ್ಲಿ ಸರ್ಕಾರದವರು ಕೊಟ್ಟಿರುವ ಸಲಹೆಗಳನ್ನು ಪರಿಶೀಲಿಸಿ ಅಭಿಪ್ರಾಯ ತಿಳಿಸುವ ವಿಷಯದಲ್ಲಿ ಆಗಿರುವ ಪತ್ರವ್ಯವಹಾರವನ್ನು ಪರಿಶೀಲಿಸಿದ ಮೇರೆಗೆ ಸರ್ಕಾರದವರು ತಾರೀಖು 17-5-1929ನೇ ಇಸವಿಯ ಲೆಟರ್ ನಂ. 13956-7/Med. 1929-25 ನೇ ನಂಬರಿನ ಲೆಟರ್ -

Resolution:- ಈ ಕೌನ್ಸಿಲ್ಲಿನ ಮೆಂಬರುಗಳೆಲ್ಲರೂ ಮೇಲ್ಕಂಡ ಲೆಟರುಗಳನ್ನು ಪರಿಶೀಲಿಸಿ ಈ ಸ್ಕೀಮನ್ನು ಜಾರಿಗೆ ತರುವುದರಿಂದ ಆಗುವ ಲಾಭನಷ್ಟಗಳನ್ನು ಕುರಿತು ಚರ್ಚೆ ಮಾಡಿದ ಮೇರೆಗೆ ಸರ್ಕಾರದವರು ಕೊಟ್ಟಿರುವ ಸಲಹೆಗಳು ಬಹಳ ಪ್ರಯೋಜನಕರವಾಗಿರುವುದರಿಂದ ಸದರಿ ಸ್ಕೀಮನ್ನು ಜಾರಿಗೆ ತರುವುದು ಅವಶ್ಯವೆಂದು ಅಭಿಪ್ರಾಯಪಟ್ಟು ಸರ್ಕಾರದವರಿಗೆ ಸದರಿ ವಿಷಯವನ್ನು ತಿಳಿಸಲು ಅಭ್ಯಂತರವಿಲ್ಲವೆಂದು ಒಪ್ಪಿಗೆಯಾಯಿತು -

/Extract/

President,
Municipal Council,
Kolar Town.

Appendix F G—1

SUBJECT.....

.....

.....

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

the *192*

Date of issue 7.12.29

Signed by Mr. D.C.S

List of enclosures.....

Copied by.....

Examined by.....

Section Med

File No. 49-28

Serial No.

No. G 7951.

To The Sr Surgeon

Sir,

With ref to your Lr. o
no c627-4 dy 11-11.29 re.
improvements to the
District Hospital building
at Kolar. I am directed to
state that until the Municipal
Council is in a position to
pay its quota of the cost, there
does not appear to be any
use in pursuing the matter.

In this connection I am
also to point out that in all

over

such Cases it ~~is better to Correspond~~ before with the Local Boards addressing Govt ~~[illegible]~~ to ~~[illegible]~~.

the Concurrence of the local bodies to pay their Quotas may be obtained before addressing Govt.

I have etc

For ch Secy to Govt

VR 3/12

P. 1-49